



Tadnoll Brook around Tadnoll Mill

Hatch and or Weir issue



On the right is the photo of a small set of hatches which is upstream of the stepped weir at Tadnoll Mill.

The left-hand photo is looking downstream to the house and weir. Note the impounded water above the weir in the fore-ground.

The solution will either be to improve access over the weir OR manage the side stream and build a fish pass at the hatches, neither will be cheap.